



Power Pack

Replaces: 581726



ORDER NO.	PRICE
SIE 185754	\$119.00

Power Pack

Replaces: 581397



ORDER NO.	PRICE
SIE 185755	\$96.49

Power Pack

Replaces: 582056. Same as 18-5753 w/o Hardware Pack.



ORDER NO.	PRICE
SIE 185756	\$119.00

Power Pack

Replaces: 582453



ORDER NO.	PRICE
SIE 185758	\$67.49

Power Pack

Replaces: 582125



ORDER NO.	PRICE
SIE 185759	\$78.49

Power Pack

Replaces: 582138, 582400, 582642, 582556



ORDER NO.	PRICE
SIE 185760	\$96.99

Power Pack

Replaces: 582057
Same as 18-5754 without hardware pack.



ORDER NO.	PRICE
SIE 185757	\$114.00

Power Pack

Replaces: 581731



ORDER NO.	PRICE
SIE 185753	\$124.00

Rectifier Selection Table

H.P.	Years	Rectifier
9.9,15	1974-90	18-5709
20	1989-90 (Electric Start Only)	18-5709
25	1977-88	18-5709
28	1989-90	18-5709
30	1989-90 (Electric Start Only)	18-5709
35	1976-88	18-5709
40	1974-76,1988	18-5709
45	1989-90 (Commercial)	18-5709
45SS	1989-90	18-5709
48	1989-90	18-5709
50	1971-75	18-5708
50	1979-88	18-5709
55	1976-77	18-5708
55	1978-81,1980-90 (1)	18-5709
60	1970 (D Models Only), 1971	18-5708
60	1980-88	18-5709
60	1989-90 (EL & TL Models Only)	18-5708
SST60	1989-90	18-5708
65	1972-73, 1988-90	18-5708
70	1974-90	18-5708
75	1975-88	18-5708
85	1970-80	18-5708
88	1989-90	18-5708
90	1981-88	18-5708
100	1971,1979-80,1984-88	18-5708
115	1973-88	18-5708
125	1971-72	18-5708
135	1974 (135443,135483 Models Only)	18-5708
135	1973,1975-76	18-5708
140	1977-88	18-5708
150	1979-88	18-5708
155	1984-88	18-5708
175	1977-83	18-5708
185	1984-88	18-5708
200	1976-83	18-5708
235	1978-88	18-5708

H.P.	Years	Power Pack	H.P.	Years	Power Pack	HP	Years	Power Pack
4	1977-80, 1984	18-5758	55	1978-82	18-5758	100	1979-80	18-5759(1)
4.5	1980-84	18-5758	60	1970-71	18-5749(7)	115	1969-70	18-5748(7)
5	1984	18-5758	60	1980-84	18-5758	115	1973-77	18-5753(2)
6	1977-79, 1984	18-5758	65	1968	18-5747(7)	115	1978-83	18-5759(1)(1)
7.5	1980-83	18-5758	65	1972-73	18-5754(3)	125	1971-72	18-5748(7)
9.9, 15	1977-84	18-5758	70	1974-78	18-5754(3)	135	1973-76	18-5753(2)
20	1981-84	18-5758	70,75	1979-84	18-5760	140	1977	18-5753(2)
25	1977-84	18-5758(4)	75	1975-78	18-5754(3)	140	1978-83	18-5759(1)
30	1984	18-5758	85	1968	18-5747(7)	150	1979-84	18-5760(1) (5)
35	1977-84	18-5758	85	1969-72	18-5749(7)	175	1977-78	18-5754(3) (1)
40	1982	18-5758	85	1973-77	18-5753(2)	175	1979-83	18-5760(1)
50	1971-75	18-5755	85	1978-80	18-5759(1)	185	1984	18-5760(1)
50	1979, 1981-84	18-5758	90	1981-83	18-5759(1)	200	1976-78	18-5754(3) (1)
55	1968-69	18-5747 (7)				200	1979-83	18-5760(1)
55	1976-77	18-5755	100	1971	18-5749(7)	235	1978	18-5754(3) (1)
			100	1968,72	18-5748(7)	235	1979-84	18-5760(1) (5) (6)

- (1) 2 Power Packs Required Per Engine
- (2) Order 18-5756 for Power Pack w/o cover, insulated pad & mounting screws
- (3) Order 18-5757 for Power Pack w/o cover, insulated pad & mounting screws
- (4) All Models except Worktwin, Workhorse and Commercial Model for 1983
- (5) Port side only for 1983 model STLCT
- (6) Port side only for 1984 models with suffix beginning with "S"
- (7) Pulsar Universal Pulse Pack may also be used

Rectifier 6-10 Amp

Replaces: 582399



ORDER NO.	PRICE
SIE 185708	\$34.99

Rectifier Replaces: 62351A1, 62351A2, 816770. All applications with square, 3 post rectifier.



ORDER NO.	PRICE
SIE 185707	\$34.99

Rectifier 4-5 Amp.

Replaces: 581778



ORDER NO.	PRICE
SIE 185709	\$34.99